

ISHIDA WM-Ai AUTO WRAPPER VIRTUAL TROUBLESHOOTING RELEASE NOTES

Warning: This utility is the property of Ishida Co. Ltd. Access is limited to Rice Lake Weighing Systems and its authorized resellers. This utility is intended for trained service personnel and should not be made available to end users.

The WM-Ai virtual troubleshooting utility contains a list of error codes and check points, wiring diagrams and schematics, and a virtual machine that can be used to access various menu steps. This utility program operates in a web browser.

No installation is required. Unzip the file in a suitable location. Double click the ***index.html*** file to launch the utility program. Or, right click the ***index.html*** file and create a shortcut that can be placed on the computer's desktop for quick access.



ISHIDA WM-Ai AUTO WRAPPER VIRTUAL TROUBLESHOOTING RELEASE NOTES

Version 12 features & changes [27 April 2022]

The following lists the main changes from the previous version.

1. Updated the following error:
 - 0312: Label Is Remaining.
2. Added the following errors:
 - 0395: Auto Infeeder Is Not Connected (B-type).
 - 3017: Cannot Differentiate Tray (B-type).
 - 3018: Tray is placed in front (B-type).

Version 11 features & changes [27 April 2022]

The following lists the main changes from the previous version.

1. Added a MAP section that lists all sensors and shows their location on the WM-Ai wrapper.

Version 10 features & changes [14 January 2022]

The following lists the main changes from the previous version.

1. Updated the following errors:
 - 0435: Motor Voltage Is Abnormal.
 - 0492: Film Removal Is Complete.

Version 9 features & changes [17 September 2021]

The following lists the main changes from the previous version.

1. Updated the Wiring Diagrams PDFs [Block Diagrams / System Diagrams]
 - Added a table to indicate which diagrams pertain to specific models.
 - The diagrams listed as "Non-ETL and "CS" are not used in the USA.
 - The "JWF" model is not available in the USA.
 - Updated all wiring diagrams to the latest version.
 - Combined all PDFs in to a single book of 19 pages.
 - Improved the clarify of the diagrams by converting to vector data.
 - Updated the text in the diagrams to be searchable in a web browser. Search for a motor by its "M" number, a sensor by its "B" number, or a connector by its board and "XJ number. For example:
 - M104 – applicator X-axis motor
 - B212 – rear film feeder home position
 - A200-XJ21 – connector to the A201 Front Film Feeder Movement board
2. Updated the Interlock Diagram [Block Diagrams / System Diagrams]
 - Updated CPU Board description from "P-1163 (A10)" to "P-1163/P1100 (A10)". P-1163 is not used in the USA.
3. Added an FAQ section. Please note that some items listed do not pertain to the WM-Ai wrappers available in the USA.

ISHIDA WM-Ai AUTO WRAPPER VIRTUAL TROUBLESHOOTING RELEASE NOTES

Version 8 features & changes [1 March 2021]

The following lists the main changes from the previous version.

1. Revised the layout of all printer errors:
 - 0700-**** Main printer (#1).
 - 0800-**** Second printer (#2) N/A for USA.
 - 1000-**** Bottom printer (#4), N/A for USA.
 - 1900-**** Pop printer (#5).
2. Updated the following errors:
 - 0485: Auxiliary For Magnetic Contact Is Abnormal.
 - 0609: Applicator Could Not Suck Label (Main printer).
 - 0615: Applicator Operation Is Abnormal (Pop printer).
 - 1911: Control Board For Printer Is Failed (Pop printer).
3. Added the following errors:
 - 1014: Label Remaining On Under Labeller (N/A for USA).
 - 1040: Cutter Cover Is Not Set (N/A for USA).

Version 7 features & changes [16 October 2020]

The following lists the main changes from the previous version.

1. Updated the following errors:
 - 0312: Label Is Remaining On Applicator.
 - 0351: Label Is Remaining.
 - 0485: Auxiliary For Magnetic Contact Is Abnormal Error Numbers Updated.
 - 0717: The Control Board Of Printer 1 Is Abnormal.
2. Added the following errors related to the WM-Ai-B Auto Infeed (BR) model:
 - 0511: The Feed Bar Motor Error.
 - 0512: The Loading Conveyor Motor Error.
 - 0513: The Timing Conveyor Motor Error.
 - 0514: Product Is Remaining Inside Of Infeeder.
 - 0515: Failed To Take In The Product.
 - 0516: Cover For The Infeed Is Open.
 - 0517: There Is No Product Waiting For Infeed.
 - 0518: Failed To Transport To The Wrapping Unit.
 - 0519: Automatic Infeeder Is Off.
 - 0520: Automatic Infeeder Is Not Connected.
 - 0521: The Tray Is Placed In Front.
 - 0526: Shutter Operation Of PS-AI Is Abnormal.

Version 6 features & changes [20 April 2020]

The following lists the main changes from the previous version.

1. Updated error 0402: No Response From Wrapper.

ISHIDA WM-Ai AUTO WRAPPER VIRTUAL TROUBLESHOOTING RELEASE NOTES

Version 5 features & changes [25 January 2020]

The following lists the main changes from the previous version.

1. Added Wiring Diagram schematics. Note that searchable schematics are included in the WM-Ai Service Manual 15th edition p/n 171044 available on the Rice Lake web site.
2. Added a parts list of all components with ID numbers such as A100, B202, etc. Note that the WM-Ai section in the April 2020 Wrapper Replacement Parts catalog also includes component ID numbers. It is available on the Rice Lake web site
3. Add two System Diagrams:
 - Communication wiring between each board.
 - Safety Switch Interlock wiring.

Version 4 features & changes [6 September 2019]

The following lists the main changes from the previous version.

1. Added Virtual Machine that provides access to the wrapper's menu screens.
2. Added error 0392: Check Sell By Date - Older Than The Current Time.
3. Updated error 0472: There Is A Problem On Wrapping Controller.

Version 3 features & changes [21 May 2019]

The following lists the main changes from the previous version.

1. Added the following errors:
 - 0414: Film Driving Motor Is Abnormal.
 - 0462: Film Over Error For The Lower.

Version 2 features & changes [20 December 2018]

The following lists the main changes from the previous version.

1. Updated the following errors:
 - 0312: Label Is Remaining On Applicator.
 - 0333: It Cannot Differentiate Tray.
 - 0334: Tray Is Not Programmed.
 - 0335: Close Tray Is Programmed.
 - 0402: No Response From Wrapper - Main Board to P-1105 [A200].
 - 0407: Temporary Blackout On Console.
 - 0412: Motor For Film Change Is Abnormal.
 - 0419: Motor Front Feeder Move Is Abnormal.
 - 0421: Feed Bar Motor Is Abnormal.
 - 0422: Centering Motor Is Abnormal.
 - 0423: Lift Change Is Abnormal.
 - 0435: Motor Voltage Is Abnormal.
 - 0472: There Is A Problem On Wrapping Controller.
 - 0475: Wrong Selection For Big/Small Lift.
 - 0480: Film Is Remaining.
 - 0482: Insert Plate Is Not Back To Original Position.

ISHIDA WM-Ai AUTO WRAPPER VIRTUAL TROUBLESHOOTING RELEASE NOTES

- 0485: Auxiliary For Magnetic Contact Is Abnormal.
- 0494: Problem On Wrapping Part - Application Program Is Not Installed.
- 0498: Problem On Wrapping Part - Wrapper System Is Abnormal.
- 0602: No Response From Applicator.
- 0615: Applicator Operation Is Abnormal.
- 1502: No Response From Tray Detector.
- 0312-0001: Label Is Remaining On Applicator (Pop labeler version).
- 0312-0002: Pop Label Is Remaining (Pop labeler version).

Version 1 features & changes

The following lists the main changes from the previous version.

1. Initial release.



© Rice Lake Weighing Systems Specifications subject to change without notice.
Rice Lake Weighing Systems is an ISO 9001 registered company.

230 W. Coleman St. • Rice Lake, WI 54868 • USA
U.S. 800-472-6703 • Canada/Mexico 800-321-6703 • International 715-234-9171 • Europe +31 (0)26 472 1319

www.ricelake.com/retail

www.ricelake.mx

www.ricelake.eu

www.ricelake.co.in